### AL'S SEPTIC PUMPING SERVICE, INC. 528-0432 541-8283 773-0123 927-1722 P.O. BOX 6996 LOS OSOS, CA 93412

# Invoice

| Date     | Invoice # |
|----------|-----------|
| 3/7/2023 | 37142     |

| Bill To                          | . *      |   |  |  |
|----------------------------------|----------|---|--|--|
| Randall 1<br>9165 Ha<br>Atascade | rvest Wa | • |  |  |

Seller: Randall Partin, Trustee
9165 Harvest Way
Atascadero, CA 93422
cc; Tracy Ronca @ Compass RE

| P.O. No.   | Terms                               | Due Date      | Maintenand | ce Leach Failure | Escrow     | Other  |
|--|-------------------------------------|---------------|------------|------------------|------------|--------|
| PL2/15/2023  | Due on receipt                      | 3/24/2023     |            |                  | pre-escrow |        |
|  | Description                         |               |            | Qty              | Rate       | Amount |
| Service call to locate, pump and inspect septic tank and system for an escrow sale.*System is equipped with a Lift station with effluent pump. Tank and lift station have riser access.  02/23/2023 Pumping and disposal of septic waste |                                     | uipped<br>and |            | 825.00           | 825.00     |        |
| tank and lift station- transport to Santa Maria Treatment plant. Tank has riser access to grade (tank is apprx. 7' depth) Filter on outlet side compartment.   |                                     | 1             |            |                  |            |        |
| *effluent filter in outlet of tank must be routinely pulled and cleaned. Recommended every 6 months to yearly at minimum. Has riser access to do this. Filter was pulled and cleaned and reinsert back to outlet line.                   |                                     | months this.  |            | 75.00            | 75.00      |        |
|  | full upon receip<br>nce charge 1.5% |               | not paid v | within 30 days   | Total      |        |
|  |                                     |               |            | Payments/Cred    | dits       |        |
|  |                                     |               |            |                  | Balance Du | 1e     |

### AL'S SEPTIC PUMPING SERVICE,INC. 528-0432 541-8283 773-0123 927-1722 P.O. BOX 6996 LOS OSOS, CA 93412

# Invoice

| Date     | Invoice # |
|----------|-----------|
| 3/7/2023 | 37142     |

| Bill To   |  |
|---|--|
| Randall Partin<br>9165 Harvest Way<br>Atascadero, CA. 93422 |  |

Seller: Randall Partin, Trustee
9165 Harvest Way
Atascadero, CA 93422
cc; Tracy Ronca @ Compass RE

| P.O. No.  | Terms             | Due Date  | Maintenar | nce Le | ach Failure | Escrow        | Other  |
|---|-------------------|-----------|-----------|--------|-------------|---------------|--------|
| PL2/15/2023   | Due on receipt    | 3/24/2023 |           |        |             | pre-escrow    |        |
|   | Description       |           |           |        | Qty         | Rate          | Amount |
| 02/23/20 Pump tech out to site for visual and inspect of lift station: *lift station is very deep, 15'. Pump and components checked and operable on day of inspection service. Pump was activated to test and did not observe any daylighting in area. Working at this time. Also checked the alarm set up that is located next to the Lift station on a post.  pump stations are not guaranteed against lack of maintenance, landscape vegetation/root infiltration, abuse to system (grease, wipes, sanitary products etc.),tenant/rental abuse or running fixture problems. Longevity to system upon use, and maintenance to septic tank recommended every 2/3 years depending on occupancy/usage. Pump station recommended to be checked yearly at minimum, again dependent on use or occupancy.  Inspection and report for an escrow |                   |           |           | 195.00 |             |               |        |
|   | full upon receips |           | not paid  | within | 30 days     | Total         |        |
| subject to fina   | nce charge 1.5%   | ó         |           |        |             | Payments/Cred | dite   |
|   |                   |           |           |        |             | r ayments/ore |        |
|   |                   |           |           |        |             | Balance Du    | 16     |

### AL'S SEPTIC PUMPING SERVICE,INC. 528-0432 541-8283 773-0123 927-1722 P.O. BOX 6996 LOS OSOS, CA 93412

# Invoice

| Date     | Invoice # |
|----------|-----------|
| 3/7/2023 | 37142     |

| Bill To                            |
|------------------------------------|
| Randall Partin<br>9165 Harvest Way |
| Atascadero, CA. 93422              |

Seller: Randall Partin, Trustee
9165 Harvest Way
Atascadero, CA 93422
cc; Tracy Ronca @ Compass RE

|   |                               |   | _              |                   |               |                     |
|---|-------------------------------|---|----------------|-------------------|---------------|---------------------|
| P.O. No.  | Terms                         | Due Date  | Maintenar      | nce Leach Failure | Escrow        | Other               |
| PL2/15/2023   | Due on receipt                | 3/24/2023   |                |                   | pre-escrow    |                     |
|   | Description                   | l   |                | Qty               | Rate          | Amount              |
| by numerous f<br>soil characteri<br>maintenance. observations be<br>provided by the<br>agent. It is not<br>inspection date.<br>Thank you for<br>Please remit co | the opportunity heck payment. | g but not limite, and proper is based on and information or representately stem adequate to be of services. | on ive cy past |                   |               |                     |
| To be paid in full upon receipt. All invoices not paid subject to finance charge 1.5%   |                               |   | not paid v     | within 30 days    | Total         | \$1,345.00          |
|   |                               |   |                |                   | Payments/Cred | its \$0.00          |
| License # 883281  |                               |   |                |                   | Balance Du    | <b>e</b> \$1,345.00 |

### Al's Septic Pumping Service, Inc.

Residential & Commercial Septic Tank Locating, Inspection Service and Maintenance
P.O. Box 6996 Los Osos, CA. 93412
Septic Tank and Leach System Repairs License # 883281
805-528-0432 • 541-8283 • 773-0123 • 927-1722 • 928-0887 • 466-4689

# Septic Inspection Order/Authorization Personal Guarantee of Payment

This contract binds you legally and obligates you financially. Please read it carefully.

One of the following descriptions will apply to your situation and describes terms of payment and payer obligations for each.

| .) | Property listed through realtor, Owner or Owners representative is responsible for payment: Al's Septic Pumping Service, Inc. agrees to extend short term credit for amount of billing without accruing finance charges for up to 30 days as a courtesy for listing with a professional realtor. Owner agrees to instruct the title company to pay our invoice in full upon close of escrow. Owner, Realtor, or designee, agrees to immediately pay our invoice in full if escrow |
|----|---|
|    | cancels, defaults, or extends past the scheduled closing date. We cannot "transfer" the charges to subsequent escrow for a property if it falls out of  |
|    | escrow. Signer personally guarantees payment.   |
| 2) | Property listed through Realtor, Prospective Buyer is responsible for payment:  |
|    | Buyer supplies major credit card information to Al's Septic Pumping Service, Inc. upon ordering the inspection, and authorizes us to bill the card for the total amount upon completion of work. Buyer personally guarantees payment.   |

Please note: We will not be responsible for accidental damage to pipes or wires that are buried over the top of the septic tank.

| Please check the applicable box below.   | Once received, we will sched     | fule the worl  | k   |
|--|----------------------------------|----------------|---|
|  |                                  |                |   |
|  |                                  |                | esponsible for payment to Al's Septic         |
| Pumping Service, Inc. either through esc | crow upon close of escrow, o     | r by check, V  | 'isa/MasterCard upon extension or             |
| cancellation of escrow.                  |                                  |                |   |
| ☐ I am the Realtor or legal representa   | ative of the owner and have      | authority to   | order work. By signing below, I agree to be   |
| personally responsible for payment to A  | l's Septic Pumping Service, Ir   | nc. through e  | escrow upon close of escrow or by check,      |
| Visa/MasterCard upon extension or can    | cellation of escrow.             |                |   |
|  |                                  | perty and ha   | ve authority to order work. By signing        |
|  |                                  |                | r the total charges or will pay with personal |
| check.                                   | er vice, inter to 2m my vice, in | acter car a ro | title total charges of will pay with personal |
|  | Signed by:                       |                |   |
| 100                                      | lall Partin                      |                | 2/17/2023                                     |
| signed (oddiane) or payment,             |                                  |                | Date:   |
| i illicitation italiant.                 | 14A9F35A4C4 Cell #: 831-24       |                | E-Mail randallpartin@sbcglobal.ne<br>Phone #: |
| Property address: 9165 Harvest Way       | , Atascadero, CA 9342            | 2              |   |
| Street                                   | City                             |                | hone #: 831-247-0667                          |
| Property owner: Randall Partin, T        | rustee                           | PI             | none #: 631-247-0007                          |
| Buyers Name:                             |                                  | Phone          | e#:   |
| Buyers Address:                          |                                  |                | E-Mail:                                       |
| Street                                   | City                             | Zip            |   |
| Escrow Company:                          | Address:                         |                | Escrow#:                                      |
| Realtor: Tracy/Stephanie Ronca           | Phone and cell #: 44 -           | 4883           | E-Mail: Tracy ronco a yoho                    |
| Cabadulad alasina data isr               |                                  |                | Trace (mag a) rom                             |

Please complete and sign form. Fax to 805-528-0485 or E-mail to Alssepticinc@gmail.com

### Al's Septic Pumping Service, Inc.

Septic Tank Locating-Inspection Service-Maintenance Service & Repairs P.O. BOX 6996 Los Osos, CA. 93412 528-0432, 541-8283, 773-0123, 927-1722, 466-4689

Certification-Report of Inspection-Individual Sewage Disposal System

| Date: 2/23/2023Escrow#n/a pre-escrow Owner/Seller Randal Partin, Trustee  |
|---|
| Property Address: 9165 Harvest Way Atascadero, Ca 93422   |
| Agent: Tracy Ronca Realtor/Finance Company: Compass RETitle Company:n/a   |
| Septic Tank   |
| Type of Tank: Concrete Fiberglass Plastic Other   |
| Tank Capacity: 1000 gal. 1200 gal. Other  |
| Tank Components: Access Lids Baffle San-Tees Pump Station Diversion Valve Filter  |
| Tank deterioration noted: None Minor Moderate Major/failed  |
| Tank was pumped completely on day of inspection. ✓ Yes ☐ No Depth to access lids within 12 inches of surface: ☐ Yes ☐ No  |
| Notes: TANK DASSED ALL CRITCRIA ON NOW OF INSDECTION ACCESS LOS TO  |
| SUPPACE. SERVICED EFFLUENT FILTER DURING FUSDELTION, TANK VERY  |
| DEEP 6'+ (RISERS HAVE BEEN INSTALLED TO GRADE.)   |
| Leach System  |
| Operating at proper level and shows no signs of failure or surfacing at time of inspection.   |
| Operating at above normal operating level. Will require upgrade or replacement to maintain sanitary conditions.   |
| Notes: LEACH IS EQUIPPED WITH LIFT PUMP. CHECKED AND FUSPECTED LIFT STATION   |
| OPERATION AND COMPONENTS, PASSED ALL ANSPECTION CRITERIA. NO SIGNS  |
| OF SURFACING EFFLIENT OVER LEACH FIELD AREA. DUMP IS VERY DEEP IS   |
| Conclusions   |
| The system was functioning properly on day of inspection.   |
| The entire system is <b>NOT</b> functioning properly at this time and will require upgrade in order to maintain sanitary conditions.  |
| Problem area Tank Leach Field (see details above)   |
| Notes: NO REPAIRS NEEDED AT THIS TIME. LIFT STATION NOT FINTALLED   |
| by AL'S SEPTIC.   |
|   |
| Recommendations   |
| The tank should be checked and pumped every 2-3 years to ensure proper operation.   |
| Systems equipped with a pump station, filter or diversion valve should be checked annually.   |
| Notes: Keep up on recommended maintenances to help ensure proper operation of   |
| system. FIlter in tank and lift station maintenances.  NOTICE TO BUYER/OWNER: This inspection is an expert disclosure of the  |
| condition of this waste disposal system. It is not a guarantee of continued   |
| performance, or condition, past inspection date. Leach systems are not designed to last indefinitely. Failures can occur at any time without notice. Trees/root systems can cause |
|   |
| premature leach failure if located near leach system. The sewer pipe from the building to the tank is not included in this inspection. Gray water diversions of any kind are not  |

part of this report or inspection.

# Al's Septic Pumping Service Inc.-Inspection Report

Page 2


Job address:

9165 Harvest Way Ataacadero, CA 93422

\* Notes: Septic system is equipped with lift station with effluent pump which assists the effluent out to a leach system area. There is alarm set up on pole next to lift station. This should sound if any issues or level issue.

Lift station as noted is quite deep. Filter in tank also to maintain.

### System Location & Site Sketch



Locations of the septic tank and leach field above are approximate only. The exact location or dimensioning is not within the scope of this inspection. Drawing is not to scale.