



INVOICE

Jim Alonso
P. O. Box 16364
Long Beach, California 90806
United States

Mobile: 5627390119

BILL TO
Caitlyn Cahill
3360 Kallin Ave
Long Beach, 90808

Estimate Number: 017
Estimate Date: September 24, 2025
Valid Until: September 24, 2025

Grand Total (USD): \$150.00

Services	Price	Amount
----------	-------	--------

Client Report: Camera Sewer Line Inspection Property: 3360 Kallin Ave, Long Beach, CA 90808	\$150.00	\$150.00
---	----------	----------

Date of Inspection: 9/24/25

Inspection Details:

- Inspected a 4-inch drain line from the rear clean-out to the main city connection in the street using a sewer camera.
- The inspection covered the entire line from the rear of the home to the city connection point.

Findings:

- Pipe is in good condition.
- Water is flowing properly.
- No broken, collapsed, or damaged pipes.
- No signs of root intrusion.
- Sewer line is structurally sound and functioning as intended.

Attachments:

- Photos of the sewer pipe taken during the camera inspection.
- Full video of the camera inspection from the rear of the home to the city connection point.

Conclusion:

The sewer line is in good condition and does not require repairs at this time.

Grand Total (USD): \$150.00