



EAST COUNTY PUMP SERVICE
and Well Drilling

22011 JAPATUL ROAD, ALPINE, CA 91901

Location GPS:

N _____

W _____

ELEV. _____

Well and Pump Certification

Gallons Per Minute Test (GPM)

Start Time:

10:00
11:30
12:00
5
5
2:00

Date: 12-10-18

GPM:

20
20
19.35
5
5
19.35

Total Test Time: _____ Minutes

Pressure Tank: _____ No Good

Storage Tank: Size: 10.000

Casing: Size: 7"

Grounds: yes

Pump Saver: yes

Ohm: NO

Ph: 1

Volt: 230

Hp: 1.5

Potable Water Test:

Passed: X

Failed: _____

Job Site: 2577 Arroyo POCO Ln

Signature: _____

Date: 12-17-18

**This information contained on this document is accurate as of 2:00 PM (time) and 12-10-18 (date) and does not reflect future conditions. This test does not include a professional one-on-one consultation regarding the results.

L A B O R A T O R Y R E P O R T

Telephone (619) 425-1993 Fax 425-7917 Established 1928

C L A R K S O N L A B O R A T O R Y A N D S U P P L Y I N C.
350 Trousdale Dr. Chula Vista, Ca. 91910 www.clarksonlab.com
A N A L Y T I C A L A N D C O N S U L T I N G C H E M I S T S

Date: December 12, 2018
Purchase Order Number: NONE
Sales Order Number: 42567
Account Number: B.EASC

To: _____*

East County Pump Service & Well Drilling
22011 Japatul RD
Alpine, CA 91901
Attention: Dan Wasson

Laboratory Number: B4063 Customers Phone: 445-8828
Fax:

Sample Designation: _____*

One water sample received on 12/10/18 at 3:12pm,
taken on 12/10/18 at 2:00pm by Sergio Martinez
taken from 2577 Arroyo Poco Ln.

ANALYSIS: Per EPA Drinking Water, National Primary
Drinking Water Regulations.
Test Method Colilert (MMO-MUG) SM 9223B

Total Coliform is ABSENT.

Fecal Coliform (E.Coli) is ABSENT.

	Sample Result (mg/L)	Minimum Detection Limit (mg/L)	APHA Test Method No.
	-----	-----	-----
Nitrate as Nitrogen (NO ₃ -N)	2.0	0.4	4500NO ₃ D

Note: < Is the symbol for less than.
 * = Exceeds the maximum contamination level of
 10 mg/L Nitrate as Nitrogen for Drinking Water.

Laura Torres

Laura Torres
LT/js

