

If this Property is a duplex, triplex, or fourplex, this AVID is for unit # _____.

THE UNDERSIGNED, BASED ON A REASONABLY COMPETENT AND DILIGENT VISUAL INSPECTION OF THE REASONABLY AND NORMALLY ACCESSIBLE AREAS OF THE PROPERTY, STATES THE FOLLOWING:

Entry (excluding common areas): nothing noted

See attached: Entry#1-1.jpg

Living Room: nothing noted

See attached: Living Room#1-1.jpg

Dining Room: crack in wall. Some bubbling and discoloration in wall

See attached: Dining Room#1-1.jpg

Kitchen: nothing noted

See attached: Kitchen#1-1.jpg

Other Room: Laundry: nothing noted

See attached: Laundry#1-1.jpg

Hall/Stairs (excluding common areas): nothing noted

Bedroom # 1 : (master) nail pops and cracks in ceiling. Crack in wall. No doorstop

See attached: bedroom #1-1.jpg

Bedroom # 2 : no doorstop

See attached: bedroom #2-1.jpg

Bedroom # 3 : no doorstop

See attached: bedroom #3-1.jpg

Bedroom # ____ :

Bath # 1 : (master) nothing noted

See attached: bath #1-1.jpg, bath #1-2.jpg

Bath # 2 : no doorstop

See attached: bath #2-1.jpg, bath #2-2.jpg

Bath # 3 : nothing noted

See attached: bath #3-1.jpg, bath #3-2.jpg

Bath # ____ :

If this Property is a duplex, triplex, or fourplex, this AVID is for unit # _____.

Other: Storage: nothing noted
See attached: Storage#1-1.jpg

Other: _____

Other: _____

☐ See Addendum for additional rooms/structures: _____

Garage/Parking (excluding common areas): N/A

Exterior Building and Yard - Front/Sides/Back: tree branches growing over roof
See attached: Exterior#1-1.jpg

Other Observed or Known Conditions Not Specified Above: _____

This disclosure is based on a reasonably competent and diligent visual inspection of reasonably and normally accessible areas of the Property on the date specified above.

Real Estate Broker (Name of Firm that performed the inspection): Opendoor Brokerage Inc.

Inspection Performed By (Name of individual agent or broker): Javier Gomez

Inspection Date/Time: 2026-06-18 06:45:37AM Weather conditions: Scattered clouds, Temp: 58.6 F

Other persons present: N/A

By Javier Gomez  Javier Gomez Date 06/18/2026

(Signature of Associate Licensee or Broker who performed the inspection)

Reminder: Not all defects are observable by a real estate licensee conducting an inspection. The inspection does not include testing of any system or component. Real Estate Licensees are not home inspectors or contractors. BUYER SHOULD OBTAIN ADVICE ABOUT AND INSPECTIONS OF THE PROPERTY FROM OTHER APPROPRIATE PROFESSIONALS. IF BUYER FAILS TO DO SO, BUYER IS ACTING AGAINST THE ADVICE OF BROKER.

I/we acknowledge that I/we have read, understand and received a copy of this disclosure.

Buyer _____ Date _____

Buyer _____ Date _____

I/we acknowledge that I/we have received a copy of this disclosure.

(The initials below and Broker signature are not required but can be used as evidence that the initialing or signing party has received the completed form.)

Seller EE / _____

Real Estate Broker (that did NOT fill out this AVID) _____

By _____ Date _____

(Associate Licensee or Broker Signature)

© 2024, California Association of REALTORS®, Inc. United States copyright law (Title 17 U.S. Code) forbids the unauthorized distribution, display and reproduction of this form, or any portion thereof, by photocopy machine or any other means, including facsimile or computerized formats. THIS FORM HAS BEEN APPROVED BY THE CALIFORNIA ASSOCIATION OF REALTORS®. NO REPRESENTATION IS MADE AS TO THE LEGAL VALIDITY OR ACCURACY OF ANY PROVISION IN ANY SPECIFIC TRANSACTION. A REAL ESTATE BROKER IS THE PERSON QUALIFIED TO ADVISE ON REAL ESTATE TRANSACTIONS. IF YOU DESIRE LEGAL OR TAX ADVICE, CONSULT AN APPROPRIATE PROFESSIONAL. This form is made available to real estate professionals through an agreement with or purchase from the California Association of REALTORS®.

Published and Distributed by: REAL ESTATE BUSINESS SERVICES, LLC. a subsidiary of the California Association of REALTORS®

AVID REVISED 6/24 (PAGE 3 OF 3)

Javier Gomez | Opendoor Brokerage Inc. | Generated by Glide 

AGENT VISUAL INSPECTION DISCLOSURE (AVID PAGE 3 OF 3)

d38d3009-40fc-4b5e-b6b4-43128281037c





Exterior#1-1.jpg



Entry#1-1.jpg



Living Room#1-1.jpg



Dining Room#1-1.jpg



Kitchen#1-1.jpg



bedroom #1-1.jpg



bath #1-1.jpg



bath #1-2.jpg



bedroom #2-1.jpg



bath #2-1.jpg



bath #2-2.jpg



bedroom #3-1.jpg



bath #3-1.jpg



bath #3-2.jpg



Laundry#1-1.jpg



Storage#1-1.jpg