



Inspector Certification

Invoice# \_\_\_\_\_

Victor Arredondo  
Inspector ID: 15796ITC

COUNTYWIDE SEPTIC LLC  
12523 Limonite Ave. Ste. #440  
Mira Loma, CA 91752  
Phone: (951) 314-8588  
Email: [Countywide.septic@yahoo.com](mailto:Countywide.septic@yahoo.com)  
Website: [Countywidepumping.net](http://Countywidepumping.net)

Certification of existing Subsurface Sewage Disposal System

13898 Redlands Blvd Moreno Valley CA 92555  
(Property Address)

Kathryn Bush  
(Owner Name)

a. I examined the existing subsurface sewage disposal system at the above location on 02/06/2023 date and determined that the septic capacity is 1,000 gallons

There are 3 bedrooms in the dwelling, There are 24 fixture units, There are 2 bathrooms

b. There are \_\_\_\_\_ leachline(s), each \_\_\_\_\_ ft long

c. There are \_\_\_\_\_ plastic chamber(s), each \_\_\_\_\_ ft long

d. There are \_\_\_\_\_ seepage pit(s), each \_\_\_\_\_ in diameter, \_\_\_\_\_ ft deep

e.  Leach area is undeterminable **FLOW TESTED 45-min**

f. Construction of septic tank (please check one of the following):

Concrete  Fiberglass  Steel  Other \_\_\_\_\_

g. Internal dimensions of septic (length 8 ft, width 4.2 ft, depth 4.5 ft.)

h. Condition of tank:

	Yes	No
Inlet Tee Present	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Outlet Tee Present?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Two Compartments?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Need Repairs?	<input type="checkbox"/>	<input checked="" type="checkbox"/>

• If yes, see additional comments

i. While pumping the tank, did effluent flow back into tank from the absorption systems?  Yes  No

j. Prior to pumping, was the liquid level in the tank above the outlet tee?  Yes  No

k. Was the area around the lids oxidized?  Yes  No

l. Is design of system gravity feed?  Yes  No

m.  It is my opinion that the system appears to be in good working order and can be expected to function properly with proper maintenance. No repairs are necessary at this time.

n.  It is my opinion that the system is not in good working order and will not function properly without the following repairs.

ADDITIONAL COMMENTS:

Pump Septic Tank every 2 years

NO WARRANTY TO BUYER OR SELLER UNDER ANY CIRCUMSTANCE

This is a legal contract. The intention of this certification is to provide information regarding the condition of the septic system at the time of the inspection. This document may not be acceptable by the jurisdiction having authority. This document shall not be used as a permit for construction work.

\*

Kathryn Bush 02/06/2023  
(Seller's Signature)

\_\_\_\_\_  
(Intended buyer's Signature)