




Date: 6/25/26

Project address: 9242 holland st Durham CA 95928

SEPTIC SYSTEM INSPECTION

**Septic Tank Size: 1000-gallon
Leaching Field: unknown
Sludge Depth: 18"**

**Septic Tank Type: concrete
Liquid Level In Tank: full**

PROCEDURES


Introduced water into the system @ 1-5 gallons per minute for 45 minutes.

Checked condition of tank and found in proper working condition.

Checked leaching area for excessive moisture (water on ground) odor or effluent, found none. Leech lines found in working condition.

For this septic system inspection, the tank was pumped.

THERE IS NO GUARANTEE ON THE LIFE OF A SEPTIC SYSTEM. Past and future maintenance of the system and the amount of water that is ingested into the system can only determine the longevity or life of a system, as well as length of time that existing system has been in place.


Kyle Smart
Note: Passed inspection
