


LOPES SEPTIC & PUMPING SERVICE
P.O. BOX 994
HILMAR, CA 95324



2144272000000000

Treatment Tank:

Anaerobic
Aerobic
Other: _____

Cesspool
Seepage pit

Gray water tank: ✓

Multi compartment: ✓

Material of tank:

Concrete Block Steel Plastic Other: _____

Approximate Volume of Tank: 1500

Condition of Tank:	Satisfactory	Unsatisfactory	N/A
Top and lid/covers	<u>✓</u>	_____	_____
Sanitary T(s) in Place	<u>✓</u>	_____	_____
Cracks or leakage	<u>✓</u>	_____	_____
Sewage flow from house	<u>✓</u>	_____	_____
Leach lines working good @ this time	<u>✓</u>	_____	_____
Successful load test	<u>✓</u>	_____	_____

Recommended Maintenance:

6 people every year
4 people every 2 years
2 people every 3 years

Address 1085 Colorado
DR merced