#### 39D6-F48F-4701-A6B9-3C1165AB2EC3 Authentisian II



## AGENT VISUAL INSPECTION DISCLOSURE (CALIFORNIA CIVIL CODE § 2079 ET SEQ.) For use by an agent when a transfer disclosure statement is required or when a seller is exempt from completing a TDS (C.A.R. Form AVID, Revised 12/21)

This inspection disclosure concerns the residential property situated in the City of San Bernardino County of San Bernardino , State of California, described as 996 Coulter Pine Rd Crestline Ca 92325

This Property is a duplex, triplex, or fourplex. An AVID is required for all units. This AVID form is for all units (or only unit(s)

Inspection Performed By (Real Estate Broker Firm Name)

Bill O'Rafferty, Broker California law requires, with limited exceptions, that a real estate broker or salesperson (collectively, "Agent") conduct a reasonably competent and diligent visual inspection of reasonably and normally accessible areas of certain properties offered for sale and then disclose to the prospective purchaser material facts affecting the value or desirability of that property that the inspection reveals. The duty applies regardless of whom that Agent represents. The duty applies to residential real properties containing one-to-four dwelling units, and manufactured homes (mobilehomes). The duty applies to a stand-alone detached dwelling (whether or not located in a subdivision or a planned development) or to an attached dwelling such as a condominium. The duty also applies to a lease with an option to purchase, a ground lease or a real property sales contract of one of those properties.

California law does not require the Agent to inspect the following:

- Areas that are not reasonably and normally accessible
- Areas off site of the property
- Public records or permits
- Common areas of planned developments, condominiums, stock cooperatives and the like.

Agent Inspection Limitations: Because the Agent's duty is limited to conducting a reasonably competent and diligent visual inspection of reasonably and normally accessible areas of only the Property being offered for sale, there are several things that the Agent will not do. What follows is a non-exclusive list of examples of limitations on the scope of the Agent's duty.

Roof and Attic: Agent will not climb onto a roof or into an attic.

Interior: Agent will not move or look under or behind furniture, pictures, wall hangings or floor coverings. Agent will not look up chimneys or into cabinets, or open locked doors.

Exterior: Agent will not inspect beneath a house or other structure on the Property, climb up or down a hillside, move or look behind plants, bushes, shrubbery and other vegetation or fences, walls or other barriers.

Appliances and Systems: Agent will not operate appliances or systems (such as, but not limited to, electrical, plumbing, pool or spa, heating, cooling, septic, sprinkler, communication, entertainment, well or water) to determine their functionality.

Size of Property or Improvements: Agent will not measure square footage of lot or improvements, or identify or locate boundary lines, easements or encroachments.

Environmental Hazards: Agent will not determine if the Property has mold, asbestos, lead or lead-based paint, radon, formaldehyde or any other hazardous substance or analyze soil or geologic condition.

Off-Property Conditions: By statute, Agent is not obligated to pull permits or inspect public records. Agent will not guarantee views or zoning, identify proposed construction or development or changes or proximity to transportation, schools, or law enforcement.

Analysis of Agent Disclosures: For any items disclosed as a result of Agent's visual inspection, or by others, Agent will not provide an analysis of or determine the cause or source of the disclosed matter, nor determine the cost of any possible repair.

What this means to you: An Agent's inspection is not intended to take the place of any other type of inspection, nor is it a substitute for a full and complete disclosure by a seller. Regardless of what the Agent's inspection reveals, or what disclosures are made by sellers, California Law specifies that a buyer has a duty to exercise reasonable care to protect himself or herself. This duty encompasses facts which are known to or within the diligent attention and observation of the buyer. Therefore, in order to determine for themselves whether or not the Property meets their needs and intended uses, as well as the cost to remedy any disclosed or discovered defect, BUYER SHOULD: (1) REVIEW ANY DISCLOSURES OBTAINED FROM SELLER; (2) OBTAIN ADVICE ABOUT, AND INSPECTIONS OF, THE PROPERTY FROM OTHER APPROPRIATE PROFESSIONALS: AND (3) REVIEW ANY FINDINGS OF THOSE PROFESSIONALS WITH THE PERSONS WHO PREPARED THEM. IF BUYER FAILS TO DO SO, BUYER IS ACTING AGAINST THE ADVICE OF BROKER.

© 2021 California Association of REALTORS®, Inc.

## AVID REVISED 12/21 (PAGE 1 OF 3)

Buyer's Initials



("Property").

## AGENT VISUAL INSPECTION DISCLOSURE (AVID PAGE 1 OF 3)

Bill O'Rafferty, Broker, 5947 Greenfield Av	e Riverside CA 92506	Phone: 9516843000	Fax: 951.823.5521	996 Coulter Pine
Bill O'Rafferty	Produced with Lone Wolf Transactions (zipForm Edition) 717 N	Harwood St, Suite 2200, Dallas, TX 75201	www.lwolf.com	

Authentisign ID: 9E7539D6-F48	
If this Property	is a duplex, triplex, or fourplex, this AVID is for unit # ormed By (Real Estate Broker Firm Name)Bill O'Rafferty, Broker
Inspection Perf	ormed By (Real Estate Broker Firm Name) Bill O'Rafferty, Broker
Other persons i	P/Time: 03/13/2024 Weather conditions: Clear and sunny present:
THE UNDERS	IGNED, BASED ON A REASONABLY COMPETENT AND DILIGENT VISUAL INSPECTION OF THE AND NORMALLY ACCESSIBLE AREAS OF THE PROPERTY, STATES THE FOLLOWING:
Entry (excludin	g common areas):
Living Room:	wood flooring and vaulted ceiling
Dining Room:	flooring not in good condition
Kitchen:	fair to poor condition
Other Room:	loft has charring on the ceiling from a grease fire many years ago
Hall/Stairs (ex	cluding common areas): <u>carpet in entire home in poor condition</u>
Bedroom #	1 wood is pair to poor condition all rooms
Bedroom #	
Bedroom #	
Bath # <u>1</u> :	missing door to cabinet
Bath #:	
Bath #:	
Other Room:	back bedrooms flooring has inconsistencies in terms of level

AVID REVISED 12/21 (PAGE 2 OF 3)

Buyer's Initials

1

AGENT VISUAL INSPECTION DISCLOSURE (AVID PAGE 2 OF 3)

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com 996 Coulter Pine

Authentisign ID: 9E7539D6-F48F-4701-A6B9-3C1165AB2EC3

~ 4 · • • • • • • .. ..

If this Prope	rty is a duplex, triplex, or fourplex, this AVID is for unit #				
Other:	exterior of home is wood siding in fair to poor condition - some needs to be replaced - windows are old single pane and in fair to poor condition, - some need replacement - same with doors				
Other:	The owner has lived out of the courtry for more than 20 years and rented the property to a family that could be described as hoarders. There was little maintenance during that time and there is significant deferred maintenance.				
Other:	See Text Overflow Addendum (C.A.R. Form TOA) paragraph 1				
See Add	endum for additional rooms/structures:				
Garage/Par	king (excluding common areas): <u>none</u>				
Exterior Bu	ilding and Yard - Front/Sides/Back: <u>siding in fair to poor condition</u>				
Other Obse	erved or Known Conditions Not Specified Above: <u>Seller will provide all paperwork he has on the recent</u> work, red tag and clearance status				
	sure is based on a reasonably competent and diligent visual inspection of reasonably and normally areas of the Property on the date specified above.				
Real Estate	Broker (Firm who performed the Inspection) Bill O'Rafferty, Broker				
<sup>Бу</sup>	Broker (Firm who performed the Inspection)				
not include BUYER SH PROFESSIO	Not all defects are observable by a real estate licensee conducting an inspection. The inspection does testing of any system or component. Real Estate Licensees are not home inspectors or contractors. OULD OBTAIN ADVICE ABOUT AND INSPECTIONS OF THE PROPERTY FROM OTHER APPROPRIATE DNALS. IF BUYER FAILS TO DO SO, BUYER IS ACTING AGAINST THE ADVICE OF BROKER.				
Buyer	Date				
Buyer	Date				
(The initials Seller	Blake				
Real Estate By	Broker (Firm Representing Sellering 3:34:42 PM GMT Bill O'Rafferty, Broker Bill O'Rafferty, Broker Date				
	(Associate Licensee or Broker Signature)				
Real Estate By	Broker (Firm Representing Buyer) Date				
	(Associate Licensee or Broker Signature)				
© 2021, California any portion there ASSOCIATION O REAL ESTATE I APPROPRIATE I REALTORS®. It NATIONAL ASSO	A Association of REALTORS®, Inc. United States copyright law (Title 17 U.S. Code) forbids the unauthorized distribution, display and reproduction of this form, or of, by photocopy machine or any other means, including facsimile or computerized formats. THIS FORM HAS BEEN APPROVED BY THE CALIFORNIA F REALTORS®. NO REPRESENTATION IS MADE AS TO THE LEGAL VALIDITY OR ACCURACY OF ANY PROVISION IN ANY SPECIFIC TRANSACTION. A 3ROKER IS THE PERSON QUALIFIED TO ADVISE ON REAL ESTATE TRANSACTIONS. IF YOU DESIRE LEGAL OR TAX ADVICE, CONSULT AN PROFESSIONAL. This form is made available to real estate professionals through an agreement with or purchase from the California Association of is not intended to identify the user as a REALTOR®. REALTOR® is a registered collective membership mark which may be used only by members of the CICIATION OF REALTORS® who subscribe to its Code of Ethics. ad and Distributed by: STATE BUSINESS SERVICES, LLC.				

a subsidiary of the CALIFORNIA ASSOCIATION OF REALTORS® 525 South Virgil Avenue, Los Angeles, California 90020

AVID REVISED 12/21 (PAGE 3 OF 3)

AGENT VISUAL INSPECTION DISCLOSURE (AVID PAGE 3 OF 3)

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com 996 Coulter Pine Authentisign ID: 9E7539D6-F48F-4701-A6B9-3C1165AB2EC3



# TEXT OVERFLOW ADDENDUM No.

(C.A.R. Form TOA, Revised 6/23)

This addendum is given in connection with the property known as 996 Coulter Pine Rd Crestline Ca 92325, San Bernardino, ca 92325

in which and

**Daniel Leatherwood** 

is referred to as ("Buyer/Tenant") is referred to as ("Seller/Housing Provider").

("Property").

1

1) AVID, Other, third:


About a year ago, there was a significant snow story that collapsed the deck. It was removed. The storm also cause compromise in one of the joists which led to the county "red tagging" the property. An engineer and licensed contractor shored up the home and the county has inspected the work.


The foregoing terms and conditions are hereby incorporated in and made a part of the paragraph(s) referred to in the document to which this TOA is attached. The undersigned acknowledge receipt of a copy of this TOA.

Buyer/Tenant		Date	
Buyer/Tenant		Date _	
Seller/Housing Provider	Paniel Leatherwood Daniel Leatherwood	Date _	03/16/2024
Seller/Housing Provider		Date	

©2023, California Association of REALTORS®, Inc. United States copyright law (Title 17 U.S. Code) forbids the unauthorized distribution, display and reproduction of this form or any portion thereof, by photocopy machine or any other means, including facsimile or computerized formats. THIS FORM HAS BEEN APPROVED BY THE CALIFORNIA ASSOCIATION OF REALTORS®. NO REPRESENTATION IS MADE AS TO THE LEGAL VALIDITY OR ACCURACY OF ANY PROVISION IN ANY SPECIFIC TRANSACTION. A REAL ESTATE BROKER IS THE PERSON QUALIFIED TO ADVISE ON REAL ESTATE TRANSACTIONS. IF YOU DESIRE LEGAL OR TAX ADVICE, CONSULT AN APPROPRIATE PROFESSIONAL. This form is made available to real estate professionals through an agreement with or purchase from the California Association of REALTORS. It is not intended to identify the user as a REALTOR. REALTOR® is a registered collective membership mark which may be used only by members of the NATIONAL ASSOCIATION OF REALTORS® who subscribe to its Code of Ethics.

Published and Distributed by: L L B S





#### TOA REVISED 6/23 (PAGE 1 OF 1)

## TEXT OVERFLOW ADDENDUM (TOA PAGE 1 OF 1)

