City of Compton

Pre-Sale Inspection Report

From:	Willie Germany
Date:	September 19, 2024
Permit #:	BPS24-000297
Address:	2734 W CALDWELL ST

EXTERIOR:

- Remove trash and debris away from the property.

 Completed
- Cut tall grass; trim trees; vegetation away from building.

 Completed
- Roof appears to be leaking or damaged (repairs or replacement required): carport sheathing
- Weather protection (paint) has deteriorated.
- Repair or replace dry-rot: Garage roof decking
- Repair or replace broken window(s).
- Repair damaged foundation vents.
- Repair damaged perimeter fencing. ——— Completed
- Repair damaged Interior walls: holes in wall/ above toilet cabinet
- Obtain necessary approvals and permits for:
 - [x] Addition/alteration: Legalize or demolish room addition to west side of garage.
 - x Remodel: Legalize kitchen and bathroom remodel
 - [] New structure
 - [] Garage conversion
 - [] As-builts
 - [] Electrical
 - [] Plumbing
 - [] Mechanical
 - [x] Renew expired permits and schedule inspection: B17-000018 Fire damage inspection/repair.

ELECTRICAL:

- Correct unsafe/hazardous wiring: Exposed romex wiring is not permitted for exterior use or in open frame garage.
- Install Ground Fault Circuit Interrupter (GFCI) protection if ANY work has been done with in the past three (3) years, or if GFCI receptacles are not working properly.
 - [x] Kitchen counter-top areas/ Laundry area

- [] Bathroom sink and vanity area.
- [x] Garage
- [] Exterior
- [x] Label GFCI receptacle outlets
- Install smoke detectors in ALL sleeping rooms, each level and centrally located in the hallway.
- Install receptacle covers
- Replace or install new light fixture cover(s)
- Repair and/or replace light fixture(s): inoperable recessed light/ closet light
- ANY electrical repairs and/or work MUST be do ne by a California licensed contractor or a qualified electrical journeyman.

WATER HEATER:

Install seismic straps: tighten straps

PLUMBING:

- Repair or replace bathtub shower/faucet.
- Repair or re place hose bib.
- Install main water shut-off valve.
- Reglaze bathtub.

MECHANICAL:

- Condenser refrigeration lines must be properly insulated.
- Repair or replace loose register grill: supply grill not flush with ceiling.
- Replace return air filter.

MISCELLANEOUS:

- Repair or replace broken tile: exterior front step trip/cut hazard.
- Repair or replace entry lock(s): Must be 1/4 turn style for egress door.
- Provide egress window security bar with foot release.
- Submit construction one (1) sets of drawings for unpermitted work.
- Obtain necessary permits for repairs or replacements listed

•