



Public Utilities

879 Morro Street, San Luis Obispo, CA 93401-2710
805.781.7215
slocity.org

PRIVATE SEWER LATERAL INSPECTION REPORT

See BACK for video inspection requirements

From the City of San Luis Obispo Municipal Code Section 13.08.395

PROPERTY AND CONTACT INFORMATION

PROPERTY ADDRESS(ES): 1798 Alrita Street

PLUMBING COMPANY: Cornerstone Inspection DATE: March 30, 2023

CONTACT: Gus A. Vasquez PHONE: 805-290-6303

EMAIL: gus@cornerstonecentralcoast.com

LATERAL INFORMATION

LENGTH (FEET): 97 feet MATERIAL: PVC, ABS, Clay

INSTALLATION DATE: METHOD: CLOSED CIRCUIT TELEVISION (CCTV)

DESCRIBE DEFICIENCIES: Roots at a clay pipe connection near the city conection

SIGNATURES

PLUMBER: PRINT: Gus A. Vasquez LICENSE #: 155505 CREIA

SIGN: [Signature] DATE: 3-30-23

PROPERTY OWNER: PRINT:

SIGN: DATE:

SUBMIT COPY OF CCTV FOOTAGE VIA EMAIL TO:

RYAN BEECH, WASTEWATER COLLECTION SYSTEM SUPERVISOR — lateralinspections@slocity.org — 805-781-7045

https://youtu.be/YYOBT-jtES4