Southwest Inspection and Testing, Inc.
441 Commercial Way, La Habra, Ca 90631
(562) 941-2990 • (714) 526-8441 • Fax (562) 946-0026

	, ,	SWIT Job No.	Date						
REGISTERED IN	1141. 30. 51	140276	MAR. 07, 2022						
TYPE OF Reinforced Concrete				tructural Steel Asser ire Proofing	nbly _	Quality Control Wood Framing			
REQUIRED	SPECTION			☐ Asphalt					
Job Address 24934	24934 OLD STONE WAY			City SANTA CLARITA, CA. 91381					
Job Name OAKRIDGE 17 / FOUNDATION REPAIR			Permit No. BLDR191031008348 Issued By L.A. CTY.						
Type of Structure SINGLE FAMILY RESIDENCE			Architect N/A						
Material Description (type, grade, source)			Engineer WAYPOINT ENGINEERING / DANIEL B. CHU						
- SEE INSPECTION SUMMARY -			Contractor WILLIAMS HOMES						
Inspector's Name ERIC S. ALBLINGER			Subcontractor EAGLE LIFTING						
TESTS PERFORMED									
TYPE OF SAMPLE SLUMP QUANTITY IN S		QUANTITY IN S	ET ADDITIONAL REMARKS ON SAMPLE						
INSPECTION SUMMARY — LOCATIONS OF WORK INSPECTED, TEST SAMPLES TAKEN, WORK REJECTED, JOB PROBLEMS, PROGRESS, REMARKS, ETC. INCLUDES INFORMATION ABOUT - AMOUNTS OF MATERIAL PLACED OR WORK PERFORMED, NUMBER, TYPE & IDENT. NO'S OF TEST SAMPLES TAKEN: STRUCT. CONNECTIONS (WELD MADE H.T. BOLTS TORQUED) CHECKED, ETC.									
PROVIDED CONTINUOUS INSPECTION TO INCLUDE OBSERVATION OF THE PROPER CLEANING OF DRILLED									
HOLES AND THE INSTALLATION OF DRILLED-IN ANCHORS AT HELICAL PILE CONNECTION TO EXISTING									
CONCRETE PERIMETER FOOTING. REFERENCE: FOUNDATION REPAIR PLAN 2 ON SHEETS S1.0, DETAIL 5 / S1.01									
AND STRUCTURAL GENERAL NOTES ON SHEET S1.0. A TOTAL OF (4) HILTI 'KB3 HDG 1/2 x 7 LT' EXPANSION									
ANCHORS, (ICC-ES ESR-2302) WERE INSTALLED AT (2) HELICAL PILE LOCATIONS, ('HP-6' & 'HP-7'. VERIFIED 6"									
MIN. EMBED INTO (E) CONCRETE, TYP. NO DEFICIENCIES WERE NOTED. THIS WORK IS COMPLETE.									
WEATHER: CLEAR, CA	ALM, 60 DEG. U	PON ARRIVAL - CI	LEAR,	CALM, 63 DEG.	AT DEPARTURE.				
- END OF REPORT -									
					-3c11ml				
					No.				
CERTIFICATION OF COMPLIANCE				ONTINUED ON NEXT I	PAGE  F	PAGE $1$ OF $1$			
I HEREBY CERTIFY THAT !	HAVE OBSERVED	TO THE BEST OF MY		TIME IN	TIME OUT	SAMPLES			
KNOWLEDGE ALL OF THE ABOVE REPORTED WORK UNLESS OTHERWISE NOTED. I HAVE FOUND THIS WORK TO COMPLY WITH THE APPROVED PLANS, SPECIFICATION, AND APPLICABLE SECTION OF THE GOVERNING BUILDING LAWS.									
			-	10:45 AM	1:00 PM	N/A			
CIONATURE	C DECISTEDED IN	SPECTOR .							
SIGNATURE OF REGISTERED INSPECTOR REINF. CONC. 01850 L.A. COUNTY				Approved By					
SPECIALTY NO. AGENCY			Approved ByProject Superintendent						



## COUNTY OF LOS ANGELES DEPARTMENT OF PUBLIC WORKS BUILDING AND SAFETY DIVISION

## **SPECIAL INSPECTOR REPORT**

Each inspector must complete this report and mail it to the District Office where the permit was issued.

	<b>☑</b> DAILY	□ WEEKL	Y	☐ FINAL				
Report Date MARCH	07, 2022 Buildir	g Permit # UNC-BLDR1	91031008348	District Office #				
Report Date MARCH 07, 2022 Building Permit # UNC-BLDR191031008348 District Office #  Job Address 24934 OLD STONE WAY, SANTA CLARITA (STEVENSON RANCH)								
				POINT ENG. / DANIEL B. CHU				
Inspection Frequency:	☑ Continu	ous	☐ Periodic					
Type of Inspection: For any of al	have types of inspections	Gunite / Shotcret		ed Concrete				
Location on Site (2) H				DENCE (NORTH SIDE).				
Description of Work OF	SERVED THE IN	ISTALLATION (4) T	OTAL HILTI 'KE	33 HDG 1/2 x 7 LT'				
				LOCATIONS. REFERENCE:				
FOUNDATION	REPAIR PLAN 2	ON SHEET S1.0,	DETAIL 5 / S	1.01 AND STRUCTURAL				
GENERAL NO	TES ON SHEET	S1.0. VERIFIED	6" MIN. EMBE	D INTO EXISTING				
CONCRETE FOO	OTING, TYP. THIS	S WORK IS COMPL	ETE.					
Discrepancies NONE	WERE NOTED							
All work on this job to date HAS / HAS NOT been satisfactorily completed in conformance with the approved plans and requirements of the Los Angeles County Building Code.								
Signature	ma	LA CO ID#	01850 Da	MARCH 07, 2022				
Brint Full Name ERIC	S. ALBLINGER	/	Daytime Phone #	805-402-8689				