



West Coast Chief Repair, Inc

Air Conditioning, Heating, Refrigeration and
Appliances

3300 N San Fernando Blvd. Unit 101
Burbank, California 91504 United States
Phone #323-782-3922

Email: Service@chiefappliance.com
Web: www.chiefappliance.com

Send Payment to : P.O Box 46779 , Los Angeles, CA
90046

Estimate 475442115

Job 862509

Estimate Date 9/23/2022

Customer PO

Billing Address

Antonio Jaramillo
215 North Kenwood Street #APT 106
Glendale, CA 91206 USA

Job Address

Antonio Jaramillo
215 North Kenwood Street
#APT 106
Glendale, CA 91206 USA

Estimate Details

Hydronic System Repair: Blower motor failure

| Task # | Description | Quantity | Your Price | Your Total |
|--------------|--|----------|------------|------------|
| HVAC Service | Need to replace double shifts blower motor 3 speed, 2 blower wheels; replace capacitor, 2 blower wheels and perform deep maintenance for evaporator coil and blower wheels housings. | 1.00 | \$1,899.00 | \$1,899.00 |

Sub-Total \$1,899.00

Total \$1,899.00

Thank you for choosing West Coast Chief Repair, Inc

Invoice is now Due

For your convenience, a link is provided for payment in the email.
We are also available by phone to take your payment at (323) 782-3922

THIS IS AN ESTIMATE, NOT A CONTRACT FOR SERVICES. The summary above is furnished by West Coast Chief Repair as a good faith estimate of work to be performed at the location described above and is based on our evaluation and does not include material price increases or additional labor and materials which may be required should unforeseen problems arise after the work has started. I understand that the final cost of the work may differ from the estimate, perhaps materially.

THIS IS NOT A GUARANTEE OF THE FINAL PRICE OF WORK TO BE PERFORMED. I agree and authorize the work as summarized on these estimated terms, and I agree to pay the full amount for all work performed.