

County of San Diego

Department of Environmental Health and Quality

Land and Water Quality
5500 Overland Ave., Suite 210, San Diego, CA 92123 / (858) 565-5173
www.sdcdehq.org

ONSITE WASTEWATER TREATMENT PERMIT PERMIT EXPIRATION DATE: 12/7/2022

RECORD ID: DEH2021-LSTP-006255
3208 DAKWOOD DR. JULIAN

OWNER: ADDRESS: MILLER MICHAEL M

4919 CORTE PLAYA ENCINO

SAN DIEGO, CA 92124

PROFESSIONAL: Patrick Brown

PATRICK ENGINEERING & SURVEYING

760-765-1343

SITE:

PARCEL:

NO ADDRESS, CA

291-242-82-00

This PERMIT is issued for the following: Conventional Permit - New

Commercial / Residential: Residential

Gallons / Day: 300

LAYOUT RECORD ID:

Number of Bedrooms: 2

Source of Portable Water: Public Water Supply

Water District:

ONSITE WASTEWATER SYSTEM DETAILS

Primary Septic Tank (in gallons): 1000

Soil Disposal System: Horizontal Seepage Pit

Pit Length: 75 ft. Pit Depth: 6 ft. Pit Width: 4 ft. Cap Depth: 1 ft.

COMMENTS:

Open Game Room not to be counted or used as bedroom for septic sizing purposes.

ANY CHANGES IN THE ABOVE DESIGN MAY VOID THE PERMIT

THIS PERMIT IS NOT TRANSFERABLE

INSPECTION REQUEST PHONE LINE: 858-694-2553

This permit is provisional. The Director or designee of the Director may order that the Permit or any permit element be denied, suspended or revoked for violation of any relevant requirement established or provided by law.



COUNTY OF SAN DIEGO DEPARTMENT OF ENVIRONMENTAL HEALTH LAND AND WATER QUALITY DIVISION


Project#: LSTP-DOGZES

DATE: 1/4/02 2077

APN#: 291-242-82

5500 Overland Ave, Suite 210, San Diego, CA 92123 (858) 565-5173

	INSPECTION REPORT				
_	New		DISAPPROVED		
M	APPROVED INSPECTION TYPE		REINSPECTION FEES REQUIRED		
Site A	ddress: 3208 OAKwood Dr	City: <u>Su</u>	idan		
<u>7</u> 5	5' Horrental supage pit insta	alled	REINSPECTION FEES REQUIRED		
	1 55' H-pit & total of 75	(
P:1	+ depth at (e', 4' width, #	T' cap			
100	o callon intoltrator touck	install	· Q		
te	ul.				
ST					
9	releve to serve a 2 B	12 SFS			
As-		PROPERTY COME AND A TRANSPORT			
MV	SVOTICOS TO POUR TVI		*		
-	DISAPPROVED DISAPPROVED REINSPECTION TYPE REINSPECTION FEES REQUIRED				
INST	ALLED BY: Black burn Sommers	DISAPPROVED REINSPECTION FEES REQUIRED			
014 T		= ,			
AS-B	BUILT PROVIDED BY CONTRACTOR 🔀 YES 🔲 NO- MU	ST BE SUBMIT	TED		
	This Section for Repair/Modification Permits	Only			
	Permit issued for sewage disposal system repair purposes only. A postundard repair has been installed that may limit the long term po	rformanca (Saa I	Janair Janair		
	Authorization Comments).	inomance (See i	(epail		
	No building permits are to be approved that would increase the sewage demand on the septic system, occupancy of the structure, or encroach upon the sewage disposal system because of the limited sewage disposal area available.				
	to public sewer because no additional area exists on the site for a stand	dard repair.			
SPE	CIALIST: PHONE:	1019-1079	1-4375		



COUNTY OF SAN DIEGO DEPARTMENT OF ENVIRONMENTAL HEALTH (DEH) LAND AND WATER QUALITY DIVISION

SAN DIEGO OFFICE 5500 Overland Avenue San Diego, Ca 92123 (619) 565-5713

	SITE: 3208 Oakword Orive			
OWNER: Mike Miller	APN: 291- 242-4343 -82			
MAILING ADDRESS:	DEH CERTIFICATION: Percolation test			
PHONE:	PROJECT #: DEH 2019_ LOUTS-011146			
This project is approved with the following conditions noted:	FOR DEH USE ONLY			
Specialist: Date: 10-20-19				
CONDITIONS	Septic Tank (in gallons): /000			
1 100' to water well (tank and lines /150' to H-pits/	Leach Line: Length *ft (+100% reserve)			
1/4 mile for V pits).	Trench Depth Rock Below Pipe			
 100' to high water line or creek or pond. \$\sum_{5:1}\$ setback to cut bank or slope greater than 60% 	Horizontal Pit: Length 75' Cap: 1'			
(5' horizontal for every 1' vertical up to 100') 4 5:1 setback to ultimate road improvement cuts.	Vertical Pit: Depth:Cap:			
5 Maintain 25' setback to water main/easement.6 Drainage course setback of 50' from edge of	This system is approved to serve a bedroom dwelling.			
flowline. 7.	THIS IS NOT A SEPTIC PERMIT!			
adjacent lot(s). 8. Setback to underground utility trenches (5:1). 9. X Maintain required setbacks (paved areas and driveways require setbacks).	NOTE: YOU HAVE ONE YEAR TO OBTAIN A SEPTIC TANK PERMIT. HOWEVER, A SITE RECHECK MAY BE REQUIRED AT ANY TIME TO DETERMINE IF SITE CONDITIONS HAVE CHANGED.			
Septic tank to all structures is 5'. Leach lines to all structures is 8'. Seepage pit to all structures is 10'. 10. Slopes exceed 25% (see special conditions).	ADDITIONAL REQUIREMENTS TO BE COMPLETED PRIOR TO THE			
11. X System to be located in native, undisturbed soil	ISSUANCE OF A SEPTIC PERMIT			
 X_System to be located in approved, tested area. X_Leach lines to follow contour of land. X_Plumbing fall to allow standard trench depth. X_Tank to be installed in native material. *ADD 20% TO LEACH LINE LENGTH WITH 	REVIEW OF GRADING BY DEH STAFF (CALL YOUR SPECIALIST AFTER GRADING IS COMPLETED IF NOT SIGNED OFF BELOW) REVIEW OF STAMPED BUILDING PLANS			
INFILTRATOR 24 CHAMBER*	DEH GRADING INSPECTION: None proposed			
COMMENTS:	C. M. DIRDING T. PANNSVIEW.			
treatment system with 420 ft of deip	VERIFICATION OF POTABLE WATER SOURCE: A or B			
dispersal once This one is to confully				
cleared of all woody plants/trees prior to	A) WELL (Lab Number and Date):			
final approval. This area stall be maintained free of such vertebrion and shall not	B) Public Water Supply (Purveyor): Magazinic Pines & O			
he disturbed until its use is required.	FOR DEH USE ONLY: OK To issue Septic Permit Date			
Horizontal pit dimensions: 6' deep, 4'width, 1 7' total depth.	OK to issue Building Permit Date			



COUNTY OF SAN DIEGO

DEPARTMENT OF ENVIRONMENTAL HEALTH PERCOLATION TEST REPORT

DEH Control #:	Lowrs-07/146
Date:	
Activity Code: _	1

Co ENVIROR	A STATE OF THE STA						
ssessor	's Parcel Number:	291-242-49,43		Map #1958	B Lot#	19 & 12	
ite Addr	ess 3208 Oakwood	Drive		Town: _Julian	Zip C	ode: <u>92036</u>	
Owner: Mike Miller				Phone: <u>(619) 980-6699</u>			
lailing A	ddress: P. O. Box	442, Julian, CA	92036				
Test Hole #	Test Depth	Stabilized Rate	Test Hole #	Test Depth	Stabilized Rate	Average Perc Rate	
1	3'	9.25	1	1'	22.7	19.8 Min/Inch	
2	6'	31,25	2	1'	14.7	- and	
3	4'	22.70	3	1'	11.0		
4	6'	17.80	4	1'	16.0	15.7 Min/Inch	
5	8' naga pita: Provide solis	17.85	5	1'	14.0		
eptic Ta each Li	MENDATIONS: ank: N/A ne Length: N/A	ft Seepag	e Pit Type	8/2 	lumber of Pits: _	0 gal	
ench C	Depth: N/A	ft Length:		75 ft V	Vidth:		
ock bel	ow Pipe: N/A	in Total D	epth:	7_ft C	ap Depth:	ft	
	N/A						
ropose	d Structure:Two	bedroom single	family dwell	ing		****	
	SUPPLY: of Potable Water:	Majestic Pines	Water Distri	ct Well Pe	rmit Number:	N/A	
have rev	lewed this percolation lesign to be accurate	n data and design and in complian	of the subs	surface sewage dispo and local regulation	sal system for this s, and good engin	s parcel and find sering practice.	
egistered	I CE, PE, Geologist, RI		OWN, RCE #1	514WY 18087	***************************************		
ddress: _	P. O. Box 442. Julian.		Phone:		Date:	10/01/2019	
		FOI	R DEPARTM	ENT USE ONLY			
Approved: Yes No Date: 10-26-19 Specialist:			_ Final Map	Final Map Required: Yes No _K			
	Plan Review:	reminime, c	1.2. HERRITE 11.2. HERRITE	Date:	Date:		
	Inspection:	nla		Date:			
vater S	ample Analysis Re	Bults:	-	Date:			