

AGENT VISUAL INSPECTION DISCLOSURE

(CALIFORNIA CIVIL CODE § 2079 ET SEQ.)

For use by an agent when a transfer disclosure statement is required or when a seller is exempt from completing a TDS (C.A.R. Form AVID, Revised 12/21)

This inspection	n disclosure concerns th	e residential property situated in the City of	Palm Springs
County of	RIVERSIDE	, State of California, described as	2403 Oakcrest Drive
			("Property").

This Property is a duplex, triplex, or fourplex. This AVID form is for unit # _____. Additional AVID forms required for other units.

Inspection Performed By (Real Estate Broker Firm Name) <u>Keller WIlliams Realty Palm Springs</u> California law requires, with limited exceptions, that a real estate broker or salesperson (collectively, "Agent") conduct a reasonably competent and diligent visual inspection of reasonably and normally accessible areas of certain properties offered for sale and then disclose to the prospective purchaser material facts affecting the value or desirability of that property that the inspection reveals. The duty applies regardless of whom that Agent represents. The duty applies to residential real properties containing one-to-four dwelling units, and manufactured homes (mobilehomes). The duty applies to a stand-alone detached dwelling (whether or not located in a subdivision or a planned development) or to an attached dwelling such as a condominium. The duty also applies to a lease with an option to purchase, a ground lease or a real property sales contract of one of those properties.

California law does not require the Agent to inspect the following:

Areas that are not reasonably and normally accessible

- Areas off site of the property
- Public records or permits

• Common areas of planned developments, condominiums, stock cooperatives and the like.

Agent Inspection Limitations: Because the Agent's duty is limited to conducting a reasonably competent and diligent visual inspection of reasonably and normally accessible areas of only the Property being offered for sale, there are several things that the Agent will not do. What follows is a non-exclusive list of examples of limitations on the scope of the Agent's duty.

Roof and Attic: Agent will not climb onto a roof or into an attic.

Interior: Agent will not move or look under or behind furniture, pictures, wall hangings or floor coverings. Agent will not look up chimneys or into cabinets, or open locked doors.

Exterior: Agent will not inspect beneath a house or other structure on the Property, climb up or down a hillside, move or look behind plants, bushes, shrubbery and other vegetation or fences, walls or other barriers.

<u>Appliances and Systems:</u> Agent will not operate appliances or systems (such as, but not limited to, electrical, plumbing, pool or spa, heating, cooling, septic, sprinkler, communication, entertainment, well or water) to determine their functionality.

<u>Size of Property or Improvements:</u> Agent will not measure square footage of lot or improvements, or identify or locate boundary lines, easements or encroachments.

<u>Environmental Hazards</u>: Agent will not determine if the Property has mold, asbestos, lead or lead-based paint, radon, formaldehyde or any other hazardous substance or analyze soil or geologic condition.

<u>Off-Property Conditions</u>: By statute, Agent is not obligated to pull permits or inspect public records. Agent will not guarantee views or zoning, identify proposed construction or development or changes or proximity to transportation, schools, or law enforcement.

<u>Analysis of Agent Disclosures</u>: For any items disclosed as a result of Agent's visual inspection, or by others, Agent will not provide an analysis of or determine the cause or source of the disclosed matter, nor determine the cost of any possible repair.

What this means to you: An Agent's inspection is not intended to take the place of any other type of inspection, nor is it a substitute for a full and complete disclosure by a seller. Regardless of what the Agent's inspection reveals, or what disclosures are made by sellers, California Law specifies that a buyer has a duty to exercise reasonable care to protect himself or herself. This duty encompasses facts which are known to or within the diligent attention and observation of the buyer. Therefore, in order to determine for themselves whether or not the Property meets their needs and intended uses, as well as the cost to remedy any disclosed or discovered defect, BUYER SHOULD: (1) REVIEW ANY DISCLOSURES OBTAINED FROM SELLER; (2) OBTAIN ADVICE ABOUT, AND INSPECTIONS OF, THE PROPERTY FROM OTHER APPROPRIATE PROFESSIONALS; AND (3) REVIEW ANY FINDINGS OF THOSE PROFESSIONALS WITH THE PERSONS WHO PREPARED THEM. IF BUYER FAILS TO DO SO, BUYER IS ACTING AGAINST THE ADVICE OF BROKER.

© 2021 California Association of REALTORS®, Inc. AVID REVISED 12/21 (PAGE 1 OF 3) Buyer's Initials X___/X___Seller's Initials X___/X___ AGENT VISUAL INSPECTION DISCLOSURE (AVID PAGE 1 OF 3) Keller Williams Realty, 435 N. Indian Canyon Drive Palm Springs CA 92262 Phone: 7603251900 Fax: www.lwolf.com Fax: www.lwolf.com You Canyon Drive Palm Springs CA 92262 Phone: 7603251900 Fax: www.lwolf.com You Canyon Drive Palm Springs CA 92262 Phone: 7603251900 Fax: www.lwolf.com You Canyon Drive Palm Springs CA 92262 Phone: 7603251900 Fax: www.lwolf.com You Canyon Drive Palm Springs CA 92262 Phone: 7603251900 Fax: Williams Realty, 435 N. Indian Canyon Drive Palm Springs CA 92262 Phone: 7603251900 Fax: Williams Canyon Drive Palm Springs CA 92262 Phone: 7603251900 Fax: Williams Canyon Drive Palm Springs CA 92262 Phone: 7603251900 Fax: Williams Canyon Drive Palm Springs CA 92262 Phone: 7603251900 Fax: Williams Canyon Drive Palm Springs CA 92262 Phone: 7603251900 Fax: Williams Canyon Drive Palm Springs CA 92262 Phone: 7603251900 Fax: Williams Canyon Drive Palm Springs CA 92262 Phone: 7603251900 Fax: Williams Canyon Drive Palm Springs CA 92262 Phone: 7603251900 Fax: Williams Canyon Drive Palm Springs CA 92262 Phone: 7603251900 Fax: Williams Canyon Drive Palm Springs CA 92262 Phone: 7603251900 Fax: Williams Canyon Drive Palm Springs CA 92262 Phone: 7603251900 Fax: Williams Canyon Drive Palm Springs CA 92262 Phone: 7603251900 Fax: Williams Canyon Drive Palm Springs CA 92262 Phone: 7603251900 Fax: Williams Canyon Drive Palm Springs CA 92262 Phone: 7603251900 Fax: Williams Canyon Drive Palm Springs CA 92262 Phone: 7603251900 Fax: Williams Canyon Drive Palm Springs CA 92262 Phone: 7603251900 Fax: Phone: 7603251900

	blex, triplex, or fourplex, this AVID is for unit # By (Real Estate Broker Firm Name) <i>Keller Williams Realty Palm Springs</i>
Inspection Date/Time:	11/01/2022 1:10 PM Weather conditions: Sunny and clear
	Joseph Dauphine. Seller BASED ON A REASONABLY COMPETENT AND DILIGENT VISUAL INSPECTION OF THE
	NORMALLY ACCESSIBLE AREAS OF THE PROPERTY, STATES THE FOLLOWING:
Entry (excluding comm	non areas):
2	
Living Room:	
Dining Room:	
Kitchen: sink d	liscolored
Other Room:	
Hall/Stairs (excluding	common areas):
Bedroom # <u>2</u> : <u>Guest</u>	solar tube above bed appears to be masked; shutters appear damaged
Bedroom #:	
Bedroom #:	
8 	
Bath # 1 : Main:	sink stoppers appear to not work; sinks are discolored
Bath # 2 : Guest	: sinks are discolored
Bath # :	
Other Room:	
3	
AVID REVISED 12/21 (P	AGE 2 OF 3) Buyer's Initials X / X Seller's Initials X / X
	AGENT VISUAL INSPECTION DISCLOSURE (AVID PAGE 2 OF 3) Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com 2403 Oakcrest Dr.

If this Property is a duplex, triplex, or fourplex, this AVID is	or unit #
Other:	
Other:	
Other:	
See Addendum for additional rooms/structures:	
Garage/Parking (excluding common areas): <u>Driveway c</u>	racked and discolored
Exterior Building and Yard - Front/Sides/Back: See Tex	t Overflow Addendum (C.A.R. Form TOA) paragraph 1
Other Observed or Known Conditions Not Specified Ab	
discolored grout; artwork on walls may	leave holes in walls once removed
This disclosure is based on a reasonably competent a accessible areas of the Property on the date specified a	and diligent visual inspection of reasonably and normally bove.
Real Estate Broker (Firm who performed the Inspection)	Keller Williams Realty Palm Springs Jason S Allen
By (Signature of Associate Licensee or Broker who	Jason S Allen Date
(Signature of Associate Licensee of Broker who	performed the inspection)
	te licensee conducting an inspection. The inspection does
not include testing of any system or component. Real	Estate Licensees are not home inspectors or contractors. CTIONS OF THE PROPERTY FROM OTHER APPROPRIATE
PROFESSIONALS. IF BUYER FAILS TO DO SO, BUYER	
I/we acknowledge that I/we have read, understand and	
-	
Buyer X	Date
Buyer X	Date
I/we acknowledge that I/we have received a copy of this	
51	ence that the initialing party has received the completed form.)
Seller X /X	
Real Estate Broker (Firm Representing Seller) By(Associate Licensee or Broker Sign	Keller Williams Realty Palm Springs
By(Associate Licensee or Broker Sign	Jason S. Allen Date
	,
Real Estate Broker (Firm Representing Buyer)	
By (Associate Licensee or Broker Sigr	Date
© 2021, California Association of REALTORS®, Inc. United States copyright law (Title any portion thereof, by photocopy machine or any other means, including facsimile	17 U.S. Code) forbids the unauthorized distribution, display and reproduction of this form, or or computerized formats. THIS FORM HAS BEEN APPROVED BY THE CALIFORNIA
ASSOCIATION OF REALTORS®. NO REPRESENTATION IS MADE AS TO THE LEG	AL VALIDITY OR ACCURACY OF ANY PROVISION IN ANY SPECIFIC TRANSACTION. A ESTATE TRANSACTIONS. IF YOU DESIRE LEGAL OR TAX ADVICE, CONSULT AN
APPROPRIATE PROFESSIONAL. This form is made available to real estate pr	ofessionals through an agreement with or purchase from the California Association of is a registered collective membership mark which may be used only by members of the
NATIONAL ASSOCIATION OF REALTORS® who subscribe to its Code of Ethics.	
Published and Distributed by: REAL ESTATE BUSINESS SERVICES 11 C	

a subsidiary of the CALIFORNIA ASSOCIATION OF REALTORS® 525 South Virgil Avenue, Los Angeles, California 90020

AVID REVISED 12/21 (PAGE 3 OF 3)

AGENT VISUAL INSPECTION DISCLOSURE (AVID PAGE 3 OF 3)

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com 2403 Oakcrest Dr.



TEXT OVERFLOW ADDENDUM No. 1

(C.A.R. Form TOA, Revised 6/16)

	connection with the property known as2403 Oako	("Property"),
in which		is referred to as ("Buyer")
and	Joseph Dauphine	is referred to as ("Seller")
1) AVID, Exterior Building:		
Front walkway: concrete ci		
	cked; grout is discolored in areas; paint peeling on stuc	
some tiles cracked; grout c	discolored in some areas; paint peeling on fence; some	vegetation appears distressed

The foregoing terms and conditions are hereby incorporated in and made a part of the paragraph(s) referred to in the document to which this TOA is attached. The undersigned acknowledge receipt of a copy of this TOA.

Buyer	Date
Buyer	Date
Seller Joseph Dauphine	Date 11-2-2-7
Seller	Date

®2014, California Association of REALTORS®, Inc. United States Copyright law (Title 17 U.S. Code) forbids the unauthorized distribution, display and reproduction of this

THIS FORM HAS BEEN APPROVED BY THE CALIFORNIA ASSOCIATION OF REALTORS® (C.A.R.). NO REPRESENTATION IS MADE AS TO THE LEGAL VALIDITY OR ACCURACY OF ANY PROVISION IN ANY SPECIFIC TRANSACTION. A REAL ESTATE BROKER IS THE PERSON QUALIFIED TO ADVISE ON REAL ESTATE TRANSACTIONS. IF YOU DESIRE LEGAL OR TAX ADVICE, CONSULT AN APPROPRIATE PROFESSIONAL.

This form is made available to real estate professionals through an agreement with or purchase from C.A.R. It is not intended to identify the user as a REALTOR®. REALTOR® is a registered collective membership mark which may be used only by members of the NATIONAL ASSOCIATION OF REALTORS® who subscribe to its Code of Ethics.

L Published and Distributed by: L

REAL ESTATE BUSINESS SERVICES, LLC.

a subsidiary of the California Association of REALTORS® 525 South Virgil Avenue, Los Angeles, California 90020

TOA REVISED 6/16 (PAGE 1 OF 1)

TEXT OVERFLOW ADDENDUM (TOA PAGE 1 OF 1)

	•
4	5
	-
10	PERTUNITY

Keller Williams Realty, 435 N. Indian Canyo		Phone: 7603251900	Fax:	2403 Oakcrest Dr.
Jason S. Allen	Produced with Lone Wolf Transactions (zipForm Edition) 717 N Han	wood St, Suite 2200, Dallas, TX 75201	www.lwolf.com	